

CASPIR ARCHIVAL METADATA

Serial:	6240
Title:	Avro Anson Mk. I serial:6240 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1941-March-01. Anson s/n 6240. This accident involved 2 people. Anderson HB, Hamel E
Keywords:	RCAFAnson ,6240,5 AOS,5 Air Observer School,Stevenson Field Winnipeg,1941-March-01,Anderson,HamelRCAF L20
Created:	1941-03-01
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6240

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMMANDING OFFICERS REPORT.

Broken link rod in engine.

COMPOSITION:

11-3-51

ENGINE OPERATING NORMALLY AT TAKE-OFF

AND CRUISING UNTIL IT BECAME VERY ROUGH

AND VIBRATED. THROTTLE AND SWITCH WERE CUT

AND AIRCRAFT FLOWN TO AERODROME WHERE NORMAL

LANDING WAS MADE.

SFE/ET/MC/D/I

RECOMMENDATIONS:

PRIMARY CAUSE:

BROKEN LINK ROD IN ENGINE.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____