

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE			
CAUSES OF ACCIDENTS											
UNIT # 8 E.F.T.S. Sea Island, B.C.		COM. 4		PLACE Sea Island, British Columbia.				DATE 31-3-41		TIME 1645	
A/C TYPE Tiger Moth Kinner Bird		No. 407		CRASH CAT. C.4		SE x		ME		DAY x	
NAME		RANK		No.		DUTY		INJURIES		SERIOUS	
McCarthy, D.B.		LAC		R74877		P		Uninjured		FATAL	
Pope, L.		CF-AUBCiv.				P		Uninjured		INJURY	
Loveridge, T.		CF/AUBCiv.				Pas		Uninjured		CARD SERIAL No.	
Hone, G.		CF-AUBCiv.				Pass		Uninjured			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE	
Tiger Moth		407		Slight							
HOURS FLOWN BY PILOTS		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.	
						DUAL		SOLO			
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE	
4 31-3-41		K118 31-3-41									
NATURE OF ACCIDENT											

DUTY ON WHICH ENGAGED: McCarthur flying solo REPORT OF INQUIRY, INVESTIGATING OFFICER
Sequences flight 12, 15, 17 and 22. OR COMMANDING OFFICER'S REPORT:

MULT

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Collison in the air as both
aircraft were gliding in to land.

DATE:
COMPOSITION:

LOA/PCL
LOA/PCL/XA

RECOMMENDATIONS:

PRIMARY CAUSE:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE