

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																								
JU.	TECH.	DISOB.	NEG'NCE	INEXP'NCE	MISCEL.	INSTRUCT.	FLT. CONTR.	OTHERS	PRIMARY	FL. CONTRS.	MOV. SURFS.	STAB. SURFS.	W. STRUTS	LAND. GEAR	FLOATS	FUSE OR HULL	TAIL SKID OR W.	ENGINE MOUNT.	MISCEL.	UND'TD	PRIMARY	FUEL SYS.	COOL. SYS.	IGNIT. SYS.	LUB'N SYS.	ENG. STR.	AIRCREW A.	ENG. CONTRS.	MISCEL.	UND'TD	PRIMARY																																																								
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																																								
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																									
CAUSES OF ACCIDENTS																																																																																							
UNIT # 6 S.F.T.S. Dunnville, Ont.				COM. 1		PLACE # 6 S.F.T.S. Dunnville Ontario.										DATE 2-4-41		TIME 1610																																																																					
A/C TYPE Harvard				No. 2774		CRASH CAT. C		SE X		ME		DAY X		NIGHT		H.O. FILE																																																																							
NAME				RANK		No.		DUTY		INJURIES						SERIOUS																																																																							
Vautour, A.C.				LAC		R64920		P.		Uninjured						FATAL INJURY																																																																							
																CARD SERIAL NO.																																																																							
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																											
Harvard		2774		Slight		D14				3-4-41		INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																																					
Wasp S3H1		8470/4279 N11												3		126		126																																																																					
SIGNAL No & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																																																																			
				A 198 3-4-41																																																																																			
NATURE OF ACCIDENT																																																																																							
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																																								
CATEGORY		TYPE OF ENGINE		TYPE OF A/C		CAUSES		STAGE OF FLIGHT		MISCELLANEOUS		HAND Q.		PRIMARY		UND'TD		OTHER		AL G SURF.		DRKNS.		WEATHER		INSTS.		PRIMARY		UND'TD		MISCEL.		ENG. CONTRS.		AIRCREW A.		ENG. STR.		LUB'N SYS.		IGNIT. SYS.		COOL. SYS.		FUEL SYS.		PRIMARY		UND'TD		MISCEL.		ENGINE MOUNT.		TAIL SKID OR W.		FUSE OR HULL		LAND. GEAR		FLOATS		W. STRUTS		STAB. SURFS.		MOV. SURFS.		FL. CONTRS.		OTHERS		FLT. CONTR.		INSTRUCT.		MISCEL.		INEXP'NCE		NEG'NCE		TECH.		JU.	

DUTY ON WHICH ENGAGED:

First solo

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While landing, applied brakes too quickly and nosed over on runway.

PRIMARY CAUSE:

Inexperience and poor judgment

COURT OF INQUIRY, INVESTIGATING OFFICER LM/ANT/PCM/UBP
OR COMMANDING OFFICER'S REPORT:

Commanding Officers Report.

4-4-41

DATE:

COMPOSITION:

Squadron Leader R.L. Burnette.

RECOMMENDATIONS:

Pupil has been given further dual and the action he should have taken carefully explained.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pupil on first solo misjudged his approach and overshoot.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____