

کے		) ) ) • • • •	9 ) )	$\int \int $	))	)
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVEST	TIGATING OFFICE	ER TEALPET		) .
)		OR COMMANDING OFFICER'S REPORT:				<b>)</b> :
ĺ			COMMANDING OF	FICER'S REPORT		
•	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	10-4-41			) :
)	HARVARD 2879, OCCUPIED BY SGT. COOKE AND LAC	COMPOSITION:	• •	, WING COMMANDER		$\rightarrow$ :
	LEARNING, WAS TAXIING ALONG THE TAXI STRIP, PRO- DEEDING TO # 2 RUNWAY, FOLLOWED BY HARVARD 2975		EIG. IGEELATO.	THE CONTRIBUTE		<u> (</u> 11
)	OCCUPIED BY F/O SHOWLER AND LAC PALMER. PALMER					), ,
)	WAS HAVING DIFFICULTY WITHTHE INSTRUMENT FLYING					<b>)</b> !
•	HOOD AND PO SHOWLER LOOKED AROUND, WHILE PRO-	PECOM MENDATIONS.				
•	CEEDING QUITE SLOWLY, TO SEE HOW HE WAS GETTING ALONG. IN THE MEANTIME #2879 STOPPED PREPARATORY	RECOMMENDATIONS:				<u>:</u> ر
)	TO TAKE-OFF AND 2975 CONTINUED UNTIL PROPELLOR					
`	STRUCK TAILPLANE OF OTHER AIRCRAFT. PRIMARY CAUSE:					
,			•			) <u> </u>
)	CARELESSNESS ON THE PART OF PILOT OF 2975.	4 - <del>-</del>				つ!!
`						<b>-</b>
)		ACTION TAKEN:  (A) DISCIPLINARY (B) TI			-	<b>)</b> =
)	•					` 1
(	P/O Showler has been parabed. His Log Book has been endorsed				ED	
)		MTAXIINGCARELESSNE	E\$\$."			)
)						) :
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:					)
)	AIRSCREW OF 2975 STRUCK TAILPLANE OF 2879					)
`			i	RECORDED BY	DATE	
J						-
)						.)
`			3 3 3 3	CHECKED BY	DATE	~ :
	., .,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, , , , , , , , <b>,</b> ,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, כ כ	رر