

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER  OR COMMANDING OFFICER'S REPORT.
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Ground loop after landing. Pupil on first solo in Harvard allowed a swing to develop— failed to check it in time. Aircraft skidded sideways, damaging wing and starboard oleo leg.	OR COMMANDING OFFICER'S REPORT: AS/PSS/USS/  DATE: Commanding Officers Report.  18-4-41  Squadron Leader R.H. Burnette. (for Group Captain A.E. Hull)  RECOMMENDATIONS:  Log Book endorsed as "inexperience."
PRIMARY CAUSE: Inexperience, this being first pilot's first solo on type.	c moxper render.
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Light but variable wind may have sended to set up a swing. Pupil did not check correctly.	RECORDED BY DATE
	CHECKED BY DATE