

## CASPIR Aircraft Accident Cards

---

**Serial:** 2748

**Title:** North American Harvard Mk.II serial:2748 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1941-April-20. Harvard II s/n 2748. This accident involved 1 person. Kinsey R

**Keywords:** RAFHarvard II,2748,34 SFTS,34 Service Flying Training School,Medicine Hat Alberta,1941-April-20,KinseyRCAF L20

**Created:** 1941-04-20

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2748>



DUTY ON WHICH ENGAGED:

TRAINING FLIGHT.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

*Lucum ✓*

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

LANDED WITH UNDERCARRIAGE RETRACTED

About to land found that undercarriage was  
locked. Made dives and aerobatics for an hour  
but in vain. Was forced to land with  
wheels up.

RECOMMENDATIONS:

PRIMARY CAUSE:

REAR COCKPIT FIRE EXTINGUISHER BECAME  
DETACHED, JAMMING THE UNDERCARRIAGE  
SELECTOR LEVER IN UP POSITION.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

NIL

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_