

CASPIR Aircraft Accident Cards

Serial: 2578

Title: North American Harvard Mk.II serial:2578 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1941-April-27. Harvard II s/n 2578. This accident involved 2 people. Henderson AC, Stansfeld NK

Keywords: RAFHarvard II,2578,34 SFTS,34 Service Flying Training School,Holsom,1941-April-27,Henderson,StansfeldRCAF L20

Created: 1941-04-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2578>

DUTY ON WHICH ENGAGED:

Flying Back to Medicine Hat
Aerodrome.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT: DFM/ROA/ES/NN/O/UOK/B

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine cut out after take off.
Aircraft landed with undercarriage
retracted.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Engine cut out after taking off

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft was landed with undercarriage
retracted.

RECORDED BY

DATE

CHECKED BY

DATE