

(3)		
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER TM/ANT/PCM/USP	
) Night take-offs and landings.	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	MONTHLY ACCIDENT RETURN.	
Pilot applied brakes and aircraft went up on its nose. AFTER LANDING PIL	COMPOSITION:)	
TURNED OFF RUNMAY INTO A PRHIBITED AREA THINK!	NG)	
REALIZING HIS MISTAKE HE TRIED TO TAKE OUT OF THE AREA AND HE FAILED TO SEE AN UNLIGHTED BOU	RECOMMENDATIONS: NDARY BOUNDARY MARKINGS ARE MARKED AS OBSTRUCTIONS	
PRIMARY CAUSE: MARKER UNTIL TOO LATE.	WITH RED LIGHTS.	
> Pilot failed to see unlighted boundary marker at night until too late.	ACTION TAKEN:	
)	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
))))	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:)	
THE PILOT APPLIED THE BRAKES TOO QUICKLY.	RECORDED BY DATE	
	CHECKED BY DATE)	