



DUTY ON WHICH ENGAGED:

WIRELESS EXERCISE.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

AIRCRAFT SPUN INTO THE GROUND.

PRIMARY CAUSE:

STUNTING IN UNAUTHORIZED AIRCRAFT  
FLYING AT STALLING SPEED.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

COURT OF INQUIRY

DATE: 8-4-41

COMPOSITION:

PRESIDENT - S/L POLLOCK, W.R.

MEMBER - F/L HERVEY, V.H.

MEMBER - F/O JENNINGS, J.E.

RECOMMENDATIONS:

THAT IT BE IMPRESSED ON PILOTS THAT THEY MUST OBEY ORDERS IN  
REGARD TO THIS TYPE OF AIRCRAFT

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_