

DUTY ON WHICH ENGAGED: Both airmen
were warming up engines of their
respective aircraft.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Yale 3461 pushed one chock and swung
into starboard wing of Harvard.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

DATE: MONTHLY ACCIDENT RETURN.

POSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Starboard chock slipped from wheel
of Yale 3461. AND COLLIDED WITH HARVARD
2709

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE