

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																																				
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																														
3	2	1	4	3	2	1	4	3	2	1	4	3	2	1	4	3	2	1	4	3	2	1	4	3	2	1	4	3	2	1	4	3	2	1	4	3	2	1																																																													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																					
UNIT # 1 S.F.T.S.		COM.		PLACE		CAUSES OF ACCIDENTS										DATE: 11-5-41		TIME: 09:30																																																																																	
Camp Borden, Ont.		1		# 1 S.F.T.S.		Camp Borden										H.Q. FILE 1100-28-37																																																																																			
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																																																																																							
Harvard		2837		C5		X				X																																																																																									
NAME				RANK		No.		DUTY		INJURIES				SERIOUS																																																																																					
Sharpe W.G.				LAC		400638		P		Uninjured.				FATAL INJURY																																																																																					
														CARD SERIAL No.																																																																																					
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																							
Harvard 2837		Slight										INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																																																	
Wasp S3H1		8202/4361 Nil												DUAL SOLO		DUAL SOLO																																																																																			
																79																																																																																			
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE																																																																																			
				C85 11-5-41																																																																																															
NATURE OF ACCIDENT																																																																																																			

MISCELLANEOUS CAUSES
 HAND Q.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UND TD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STAIRY
 FATAL
 INJ.
 3RD.

DUTY ON WHICH ENGAGED:

Practising Circuits and landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

In cross winds aircraft swung
and ground looped, damaging oleo
leg, wing and airscrew.

PRIMARY CAUSE:

Carelessness on the part of the
pilot.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft ground looped on landing.

COURT OF INQUIRY, INVESTIGATING OFFICER *RS/PSS/USS/WWC*
OR COMMANDING OFFICER'S REPORT:

DATE:

Monthly Accident Return.

COMPOSITION:

RECOMMENDATIONS:

Further instruction given pilot.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____