

CASPIR Aircraft Accident Cards

Serial: 2836

Title: North American Harvard Mk.II serial:2836 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1941-May-30. Harvard s/n 2836. This accident involved 2 people. Robinson DA, Shannon CE This accident had 2 fatalities. Leading Aircraftman David Allenby Robinson RAAF Killed in Flying Accident service no:402808 Harvard 2836, Sergeant Charles Edward Shannon RCAF Killed in Flying Accident service no:R/71931 Harvard 2836

Keywords: RCAFHarvard ,2836,1 SFTS,1 Service Flying Training School,Alliston Ontario,1941-May-30,Robinson,ShannonRCAF L20

Created: 1941-05-30

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2836>

DUTY ON WHICH ENGAGED: Formation
take-offs.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

004/AOC/PSF/OF/NEN

COURT OF INQUIRY

DATE: 30-5-41

PSF/OF/N
PSF/OF/N

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot took off climbed too steeply
attempted to turn and went into
a spin and the aircraft struck the
ground and burst into flames.

COMPOSITION:

PRESIDENT / S/L AVENT, J.
MEMBER - F/O SOUTHAM, K.G.
MEMBER - F/O TRAINOR, H.C.

RECOMMENDATIONS:

NIL

PRIMARY CAUSE:

AIRCRAFT STALLING AND SPINNING WHILE DOING
A STEEP CLIMB TAKEOFF.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIRCRAFT STRUCK GROUND IN DIVE AS PILOT
ATTEMPTED TO RECOVER FROM SPIN

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____