

DUTY ON WHICH ENGAGED:

TAXIING AIRCRAFT 9548 INTO POSITION
ON TARMAC.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

AIRCRAFT 9548 COLLIDED WITH STATIONARY
ANOSN 6404.

PRIMARY CAUSE:

ERROR OF JUDGMENT.
Carelessness.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Hitting Anson 6404

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

MULT
TCA/PCT
MA/XA

DATE:

Monthly Accident Return.

COMPOSITION:

RECOMMENDATIONS:

7 days C.C. awarded to pupil and Log Book
endorsed.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY

DATE

CHECKED BY

DATE