

CASPIR Aircraft Accident Cards

Serial: R4000

Title: Fairey Battle Mk. I serial:R4000 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1941-May-06. Fairey Battle s/n R4000. This accident involved 1 person. Aggleton GM

Keywords: RAFFairey Battle ,R4000,31 SFTS,31 Service Flying Training School,Main Aerodrome Kingston,1941-May-06,AggletonRCAF L20

Created: 1941-05-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000223#R4000>

DUTY ON WHICH ENGAGED:

Taxiing after landing from Air-
to-ground firing exercises.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A.T.S. pupil pilot taxiing a/c
along the tarmac found starboard
brake ineffective when trying to turn.
Aircraft struck hangar doing slight
damage. Pupil should have switched
off in an endeavour to bring a/c
to rest.

PRIMARY CAUSE:

Starboard brake failed.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

T20/PCT/URP

Monthly Accident Return.

DATE:

COMPOSITION:

RECOMMENDATIONS:

Inverview with O.C. A.T.S.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A.T.S. pupil pilot taxiing along
tarmac lost control of aircraft
and collided with hangar.

RECORDED BY

DATE

CHECKED BY

DATE