

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																																		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																																																		
TECH.		DISOB.		NEG'NCE		INEXP'NCE		MISCEL.		INSTRUCT.		FLT. CONTR.		OTHERS		PRIMARY		FL. CONTS.		MOV. SURFS.		STAB. SURFS.		W. STRUTS		LAND. GEAR		FLOATS		FUSE OR HULL		TAIL SKID OR W.		ENGINE MOUNT.		MISCEL.		UNDT'D		PRIMARY		FUEL SYS.		COOL. SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTS.		MISCEL.		UNDT'D		PRIMARY		HAND O.		INSTS.		WEATHER		DRKMS.		ALG. SURF.		OTHER		UNDT'D		PRIMARY		TAXING		LANDING		TAKE-OFF		FLIGHT		STAIRY		FATAL		INJ.		SRD.		RAF		RAF	
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																			
CAUSES OF ACCIDENTS																																																																																																	
UNIT		COM.		PLACE		DATE		TIME																																																																																									
No. 11 SFTS		2		2 Miles N. of		21-6-41		1655																																																																																									
Yorkton				Tantallon, Sask.		H.Q. FILE		1100-37-64																																																																																									
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																																																																																					
Harvard		3764		C 5						X																																																																																							
NAME				RANK		No.		DUTY		INJURIES				SERIOUS																																																																																			
Rose, G.W. (RAAF)				LAC		402954		P		Uninjured				FATAL INJURY																																																																																			
														CARD. SERIAL NO.																																																																																			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																					
Harvard		3764		Slight.								INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.																																																																											
Wasp S3H1		9030/4589		Slight.														DUAL SOLO		DUAL SOLO																																																																													
																				100																																																																													
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE																																																																																							
A91		22-6-41																																																																																															
NATURE OF ACCIDENT																																																																																																	

DUTY ON WHICH ENGAGED:

Training

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

18/AGP/PCDE/ES/PM ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Forced landing with undercarriage retracted due to engine trouble

DATE:

Monthly Accident Return. M/I/10/8

COMPOSITION:

RECOMMENDATIONS:

Further instruction to all pilots on symptoms carburettor icing and action to be taken.

PRIMARY CAUSE:

Diagnosed icing in carburetor

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pilot did not check icing by proper use of carburettor heat.

RECORDED BY

DATE

CHECKED BY

DATE