

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE											
CAUSES OF ACCIDENTS																			
UNIT # 31 S.F.T.S.			COM.		PLACE			DATE 4-6-41		TIME 08:00									
Kingston, Ontario			1		Kingston Aerodrome			H.O. FILE		1300-R-7470									
A/C TYPE		Battle		No.		36		CRASH CAT.		SE ME DAY NIGHT									
Battle		R 7470 D				D.2		x		x									
NAME			RANK		NO.		DUTY		INJURIES		SERIOUS								
Cooper,			E0		P.		Uninjured		FATAL		INJURY								
Mabin A.E.			A/L/A		PP		Uninjured.												
<i>No record</i>																			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS							
Battle		R 7470		Slight								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.	
Merlin		118597/2747 Nil												777					
SIGNAL No. & DATE			UNIT No. & DATE			COM. No & DATE			REPORT			FILE		DATE					
			T 206 4-6-41																
NATURE OF ACCIDENT																			

CAUSES
 MISCELLANEOUS
 STAGE OF FLIGHT
 HAND O.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UND TD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 3RD.
 INJURY

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Taxiing.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Monthly Accident Return.

Wing tip and leading edge of R 7470 came in contact with rotating airscrew of another aircraft. when brakes failed to either turn or stop the aircraft.

COMPOSITION:

MULT
TCR/PBF
MA/XA

RECOMMENDATIONS:

PRIMARY CAUSE:

Failure of brakes.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Colliding with stationary Battle aircraft when taxiing.

RECORDED BY

DATE

CHECKED BY

DATE