

CATEGORY	TYPE OF ENGINE	TYPE OF A/C	CAUSES OF ACCIDENTS																																						
			PILOT	OTHERS	AIRFRAME FAILURE										ENGINE FAILURE																										
			UNIT	No. 2 B & G.			COM.	4			PLACE	15 Miles N.W. of						DATE	21-6-41		TIME	1730																			
			School, Mossbank.										Serodrome						H.Q. FILE	1022-D-1319																					
			A/C TYPE	Battle				No.	1701				CRASH CAT.	C						SE			ME			DAY	X		NIGHT												
			NAME				RANK	No.		DUTY		INJURIES						SERIOUS																							
			Lungren, R.M.				Sgt.	R75513		P		Uninjured						FATAL	INJURY																						
			Dunlop, W.E.				LAC	R75209				Uninjured																													
			TYPE A/F & ENGINE				No.	1701				EXTENT OF DAMAGE						REPORT FORM	SERIAL No.		DATE				HOURS FLOWN BY PILOTS																
			Battle																						INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.								
			SIGNAL No. & DATE				UNIT No & DATE				COM. No & DATE				REPORT				FILE				DATE																		
			A 43				22-6-41																																		
NATURE OF ACCIDENT																																									

DUTY ON WHICH ENGAGED:

Drogue Towing

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine failed at 2000 feet, pilot carried out forced landing.

DATE:

COMPOSITION:

FB/AOP/ES/NA/NA/I

RECOMMENDATIONS:

PRIMARY CAUSE: Engine Failure.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE