



DUTY ON WHICH ENGAGED:

Practice precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While executing precautionary landing, pilot failed to see telephone wires which he struck.

DATE:

Monthly Accident Return.

COMPOSITION:

1/20/PCL

RECOMMENDATIONS:

Recommended painting telephone poles white. Disciplinary action taken.

PRIMARY CAUSE:

Carelessness.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action taken. See report of 1-7-41

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE