

SPECIAL SEARCH FOR MISSING BOLINGBROKE NO. 7009 NATURE OF ACCIDENT AND STAGE OF FLIGHT: AIRCRAFT STRUCK WIRELESS MAST BABLE ISLAND IN POOR VISIBILITY.  PRIMARY CAUSE: LOW FLYING IN HEAVY FOG AND ERROR IN ALTIMETER DUE TO LOWER ATMOSPHERIC PRESSURE AT SABLE ISLAND THAN AT DARTMOUTH	OR COMMANDING OFFICER'S REPORT:  COURT OF INQUIRY  DATE:  COMPOSITION:  PRESIDENT - S/L TANNER, J.E.  MEMBER - F/L CROSSLEY, J.H.  MEMBER - F/O PRENTICE, J.H.  RECOMMENDATIONS:  ACC EAC RECOMMENDS AND IT IS CONCURRED THAT MINIMUM HEIGHT FOR PATROLS AND SEARCHES BE LEFT AT THE DISCRETION OF THE CAPTAIN OF THE AIRCRAFT AS THERE IS NO REASON WHY PATROLS AND SEARCHES SHOULD NOT BE MADE AT A LOWER ALTITUDE ESPECIALLY WITH SEAPLANES WHEN HORIZONTAL VISIBILITY IS GOOD. RECOMMEND THAT A BREAK THROUGH SHOULD NOT BE ATTEMPTED WHEN THE CEILING IS LESS THAN 600 FEET ACTION TAKEN: 2. ARRANGEMENTS BE MADE TO HAVE WEATHER REPORTS  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER /TRANSMITTED FROM SABLE /ISBAND HOURLY
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	•
O AIRCRAFT STRUCK TOP OF WIRELESS MASS AND	DECORDED BY
	RECORDED BY DATE

....

C