

CASPIR Aircraft Accident Cards

Serial: 3316

Title: Oxford serial:3316 - Crash Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1941-June-16. Oxford s/n 3316. This accident involved 1 person. Mills GR

Keywords: RAFOxford ,3316,34 SFTS,34 Service Flying Training School,Medicine Hat,1941-June-16,MillsRCAF L20

Created: 1941-06-16

340
DUTY ON WHICH ENGAGED:

Solo flying

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft overturned taking off.
After take off pupil had difficulty
in keeping the a/c straight. To prevent
running off, the throttle was manipulated,
but by the time free throttle was
obtained the a/c was bumping off and
swinging sharply to the right.

PRIMARY CAUSE:

Swung whilst taking off.

DATE:

Monthly Accident Return.

COMPOSITION:

OS/PSS

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Inexperience of pupil pilot.
Trying to manipulate the throttle to
stop swinging.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____