

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																	
CAUSES OF ACCIDENTS																															
UNIT 118 (F) Sqdn.										COM.		PLACE										DATE 20-6-41		TIME 14:50							
Rockcliffe Ont.										M.Q.		Rockcliffe Ont.										H.Q. FILE									
A/C TYPE										No.		CRASH CAT.		SE		ME		DAY		NIGHT											
Lysander II										446		D		X		X															
NAME										RANK		No.		DUTY		INJURIES						SERIOUS									
Merriam D.E.										P/O		310961		P		Uninjured.						FATAL		INJURY							
																						CARD SERIAL NO.									
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																			
Lysander		446		Slight.								INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.											
Bristol																DUAL		SOLO													
Perseus		20911/2042		N11												NOT AVAILABLE															
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE											
NATURE OF ACCIDENT																															

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

UNDTD

HAND.O.

INSTS.

WEATHER

DRKNS.

AL'G SURF.

OTHER

UNDTD

PRIMARY

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INJ

3RD.

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Practice interception.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

**Tail wheel struck a sharp depression
at the end of the runway, where the
contractors had been excavating for
the taxi strip.**

TBC/PCT

RECOMMENDATIONS:

PRIMARY CAUSE:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE