



DUTY ON WHICH ENGAGED:

**Flying Training.**

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

LUC/PCDUF/UCDL ✓

**At approx. 1200 hrs. LAC Sutton  
H.M.B., while attempting a landing,  
did not release the u/c of his  
a/c making a belly landing, thereby  
causing damage to the centre parts  
and starboard flaps, airscrew and  
oil cooler airscoop.**

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

**Failure of pilot to release u/c.**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**14 days C.B.**

**\$15.00 penal deduction.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Neglect to check u/c indicators and  
lights.**

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_