

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
INSTRUMENT FLYING	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: R 170 T86/PCT/XGM
PILOT TRIED TO GO THROUGH TOO SMALL	COMPOSITION:
A SPACE IN TAXIING TO PLACE AND REAR	
WHEEL OF AIRCRAFT WENT INTO A DITCH	
	RECOMMENDATIONS:
	NIL
PRIMARY CAUSE:	
ERROR IN JUDGMENT OF PILOT	
·	
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER PILOT'S LOG BOOK ENDORSED "CARELESSNESS"
	FILOT'S LOG BOOK ENDORSED "LARELESSNESS"
SECONDARY CAUSE OR CONTRIBUTING FACTORS: TAIL WHEEL WENT INTO DITCH	
THE WHOLE HERT THIS DITCH	RECORDED BY DATE
•	RECORDED BY DATE
	CHECKED BY DATE