



DUTY ON WHICH ENGAGED:

TAXIING ON TARMAC

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

PILOT OF AJ549 DID NOT OBSERVE AJ550  
AND TAXIED INTO REAR OF IT

PRIMARY CAUSE:

CARELESSNESS IN TAXIING BY PILOT OF AJ549

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIRCRAFT COLLIDED ON TARMAC

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

MULTI

DATE:

COMPOSITION:

TCA/PCT ✓  
TCA/XA

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

1. PP awarded P.D. 20.00
2. Log Book endorsed:-  
"Carelessness-  
taxiing accident"  
Pupil admonished.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_