

DUTY ON WHICH ENGAGED:	
DOTT ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
FLYING INSTRUCTION	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: (5/PS 5/P/PCM)
	COMPOSITION:
GROUND LOOP On cross-wind	- Control of the cont
landing a/c began to drift	
and on touching down, a/c swung	
to the right, and ground looped. Pilot did not take over control	RECOMMENDATIONS:
soon enough, and port tire blew.	
RIMARY CAUSE: Wing tip and wing were	
slightly damaged.	
Failure of pilot to apply	
sufficient rudder as a corrective	ACTION TAKEN:
measure.	(A) Disciplinary (B) Technical (C) Other
ECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Failure of the pilot to tate	
over soon enough. Too harsh	RECORDED BY DATE
and too constant an application	
of brakes.	CHECKED BY DATE