



DUTY ON WHICH ENGAGED:

SOLO FLYING TRAINING

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

LS/PSS ✓

COMPOSITION:

GROUND LOOP . At approximately  
17:50 hrs., LAC Monk. J.W.  
in a/c 2945 made a landing on No.  
3 runway, and as he was rolling down  
runway, suddenly swung to the left.

RECOMMENDATIONS:

Pilot could not correct swing and  
a/c ground looped off the runway.

PRIMARY CAUSE:

CARELESSNESS

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Failure of pilot to correct swing  
to the left resulting in a ground  
loop.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_