



DUTY ON WHICH ENGAGED:

SOLO PRACTICE

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

05/P55 ✓

COMPOSITION:

AIRCRAFT SWUNG ON TAKE OFF. LAC McKenzie,  
in a/c 3773, commencing to take-off  
in No. 1 runway, opened throttle to  
32 boost and as the tail of his a/c  
started to raise, the a/c swung to  
the left off runway where it crashed

RECOMMENDATIONS:

PRIMARY CAUSE: to the ground.

PILOT'S ERROR in that he failed to  
correct swing to the left.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft swung off runway and crashed.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_