

1))))))))))))))	
()	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	Circuits and landings.	OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 15/P55
)	PP developed a swing to starboard	COMPOSITION:
,	after landing. Although he en-	
	deavoured to check this by applying epposite rudder and brake, he could	•
	not do so, and the port main plane	RECOMMENDATIONS:
)	was damaged.	NECOMMENDATIONS:
)		
)	PRIMARY CAUSE:	• • • • • • • • • • • • • • • • • • •
)	Failing to prevent the a/c from	
(_)	swinging in its initial stage.	
(ACTION TAKEN:
1		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
		3
,)
))
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	•
)) Developing a swing to starboard after	
)	landing.	RECORDED BY DATE
)		
))))))]]]]]]]	CHECKED BY DATE
		~ , , , , , , (, ,))))))]]]]]])