

CASPIR Aircraft Accident Cards

Serial: AJ941

Title: North American Harvard Mk. II serial:AJ941 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-February-07. They are: Harvard II s/n FE350, Harvard II s/n AJ941. This accident involved 2 people. Ilett AW, Monk F

Keywords: RAFHarvard II,AJ941,41 SFTS,41 Service Flying Training School,Aerodrome,1943-February-07,Ilett,MonkRCAF L20

Created: 1943-02-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ941>

DUTY ON WHICH ENGAGED:

Taxiing.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-34
✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C AJ941 taxied into a/c FE350
which was parked, damaging stdb.
wings.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~5. Hitting other a/c.~~

9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

Disciplinary action taken against F.M.E. as well
as pupil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Carelessness, pupil taxied a/c
with airman in cockpit instead of
on wing tip.~~

RECORDED BY

DATE

CHECKED BY

DATE