

CASPIR Aircraft Accident Cards

Serial: 2859

Title: North American Harvard Mk.II serial:2859 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-February-13. Harvard II s/n 2859. This accident involved 1 person. Macauley WP

Keywords: RAFHarvard II,2859,41 SFTS,41 Service Flying Training School,Aerodrome,1943-February-13,MacauleyRCAF L20

Created: 1943-02-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2859>

DUTY ON WHICH ENGAGED:

Aerobatics and spinning.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

A/C held off too high on landing.

A/C stalled causing stbd wing to drop.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~39. Flattening out too soon.~~

4. Heavy
4

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Error of judgment.~~

~~Unbroken compacted snow surface of
aerodrome.~~

RECORDED BY

DATE

CHECKED BY

DATE