

CASPIR Aircraft Accident Cards

Serial: AH188

Title: North American Harvard Mk. II serial:AH188 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-February-17. Harvard II s/n AH188. This accident involved 1 person. Hall CH

Keywords: RAFHarvard II,AH188,41 SFTS,41 Service Flying Training School,Weyburn,1943-February-17,HallRCAF L20

Created: 1943-02-17

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AH188>

DUTY ON WHICH ENGAGED:
Solo cross country flight.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

D-14
✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Could not lower U/C for landing,
came in on belly.

DATE:
COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~34. Wheels up landing.~~

7. Other

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Fire extinguisher became dislodged
from bracket, thereby preventing
movement of U/C selector lever to
"Down" position.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____

32 1/2 Drill - in air