

CASPIR Aircraft Accident Cards

Serial: FP715

Title: Avro Anson Mk. II serial:FP715 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-February-02. Anson II s/n FP715. This accident involved 1 person. Gaunce FO

Keywords: RCAFAnson II,FP715,7 SFTS,7 Service Flying Training School,Aerodrome,1943-February-02,GaunceRCAF L20

Created: 1943-02-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP715>

DUTY ON WHICH ENGAGED:

Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

On final approach, port engine failed at 400 feet, following which stbd engine failed. Forced landing made.

DATE:

D-14

COMPOSITION:

LM/400/09/00/00/00

RECOMMENDATIONS:

PRIMARY CAUSE:

~~54. Engine failure in the air.~~

17. Forced Landing

17

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Poor airmanship and inexperience.

To Engine Trouble - accident

RECORDED BY

DATE

CHECKED BY

DATE