



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Routine bombing exercise.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

D-14

COMPOSITION:

Anson 8270 made emergency landing due to battery failure and towards end of landing ran into a/c 7430 which was taxiing ~~na~~ without lights due to battery failure.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

*6. Collision*

*6*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilots reprimanded, log books endorsed and appropriate logging forms filled in.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~neglect of pilots of both ansons to adhere rigidly to night flying procedure.~~

RECORDED BY

DATE

CHECKED BY

DATE