

CASPIR Aircraft Accident Cards

Serial: 8240

Title: Avro Anson Mk. II serial:8240 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-February-09. Anson II s/n 8240. This accident involved 3 people. McCallum WL, Reilly TE, Weir IA

Keywords: RCAFAnson II,8240,2 BGS,2 Bomb & Gunnery School,Aerodrome,1943-February-09,McCallum,Reilly,WeirRCAF L20

Created: 1943-02-09

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8240>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Landing on return from bombing exercise.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

LUC/UTB D-14 ✓

COMPOSITION:

Flat tire caused a/c to swerve off runway striking snow and causing a/c to nose up.

RECOMMENDATIONS:

PRIMARY CAUSE:

43. Tire trouble.

9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Flat tire caused by tire rupturing at very thin portion of sidewall which was aggravated by heat from brakes when taxiing for take-off.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____

Tire Burst