

101027

CF101B - SINGLE

J57-P-55

USAF No. 57-341

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT <sup>B</sup>ristol Aerospace Ltd DATE 30 Jun 70 Wpg from USAF on exchange QTO No. QT0253

Project CD No. Peace Wings

TRANSFERS 1510-21-804-5152

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
30 Jun 70	QT0253	<sup>631588, 630277</sup> Bristol Aerospace Ltd	9 Apr 75	QT0120	<sup>632309+631724</sup> ADC 409 <del>sqn</del> <del>Comox</del>
30 Jun 70 (Departed 2 Dec 70) (Returned 27/1/71)	QT0253	ADC 425 AW(F) San B <sup>ev</sup> . via LTV Greenville	24 Mar 75	ADC QT016	AG CFB Comox
17 May 71	ADL QT015	ADL 416 AW(F) <sup>630696</sup> LTF ADC AC 2 <sup>632539</sup> LTV Greenville <sup>627671</sup>	24 Mar 75	ADC QT016	CX 409 <del>sqn</del> <del>Comox</del> <sup>627671</sup>
20 Mar 72	QT0541	Bristol Aerospace Ltd <sup>630603</sup> w/fg <sup>607524</sup>	24 Mar 75	ADC QT016	AG CFB Comox
20 Mar 72	QT0541	ADL 425 AW(F) <sup>630469</sup> w/fg <sup>630690</sup>	24 Mar 75	ADC QT016	CX 409 <del>sqn</del> <del>Comox</del>
15 Jan 73	QT0401	Bristol Aerospace Ltd <sup>630469</sup> w/fg <sup>630690</sup>	15-3-79	QT0320	LX BAL <sup>632153</sup> <sup>631802</sup>
15 Jan 73	QT0401	ADC 425 AW(F) <sup>630469</sup> w/fg <sup>630690</sup>	15-3-79	QT0320	CX CFB Comox <sup>631466</sup> <sup>632158</sup>
17 Mar 75	QT0437	AG CFB <del>Magdalen</del>	28-7-81	QT0188	LX 401 BAL <sup>632534</sup> <sup>632318</sup>
17 Mar 75	QT0437	CX 425 <del>sqn</del> <del>Magdalen</del>	28-7-81	QT0188	CX 409 <del>sqn</del> <del>Comox</del> <sup>632534</sup> <sup>632318</sup>
9 Apr 75	QT0120	LX BAL w/fg <sup>630696</sup> <sup>631818</sup>	1-6-83	QT0142	CX 425 <del>Regalville</del> <sup>632343</sup> <sup>631466</sup>

## OVERHAUL DATA

DATE	QTO No.	CONTRACTOR	REPAIRS
30 Jun 70	QTO253	BAL CD2790813	Project Peace Wings Exchange Work and to ADC via ITV Greenville for FCS testing, MB5 Mod installation and painting.
20 Mar 72	QTO541	BAL 61902791801	DLR
15 Jan 73	QTO401	BAL 2798801	Engine repair to RN delivery
9 Apr 75	QTO120	BAL 2794801	DLR
25 Oct 77	QTO231	BAL 2796801	Fuel cell replacement
15-3-79	QTO320	BAL 2798801	DLR & Paint
28-7-81	QTO188	BAL 2790801	nose section rewiring