

OVERHAUL DATA							
DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
25.3.42	Time exp	Aircraft Repair			1285.05	10.5.42	# 2 TC
8.4.43		MacDonald Bros				11.6.43	# 2 TC
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD									
DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
21.12.41	C10	Regina Airport	1140	3A055 A36	2/1/42				
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re acc 1: Amson 20 184 collided with tower 604 while taking on icy surface

REMARKS:

RECORD OF WRITE-OFF							
APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS	
AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD						
FIRST ENTRY AT	114	Training Command	DATE	28/1/40	TRANSFER ORDER No.	2521
TRANSFERS			TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY	
25.3.42	Aircraft Repair	31/3 T.O. Fl 21				
10.5	#2 TC					
28.1.43	#8 R.D. Wpg. (w Res)	J.C.D 1656				
8.4.	Macdonald Bros Wpg.	T.O. D1				
11.6.	#2 TC	12/6 T.O. 1450				
4.8.44	Stored Reserve #2 T.O.	T.O. 15312				
23.10.44	#2 TC	Apdal 16765				
1.12.44	APDAL - No. 2 A.C.	T.O. 17327(33)				
16.2.45	War Assets Corporation	T.O. 18591				
	DEC. SER NO GR 2-29					

REMARKS WINTER CONVERSION SET INSTALLED AT PRAIRIE AIRWAYS LTD. QUOTATION 3/4/41 FILE 1021-22-1. (COST \$788.70).

This signed next 1320.45
 with 1050.20
 Location 202 E.H.H. De Winton

u.k. cont
 13350/13391

ENGINE TYPE	AS CHEETAH IX	UNITS	2	AIRSCREW TYPE (CODE)		REF. No.	30792/1060
BATCH No.		QUAN. IN BATCH	20/23	LEDGER FOLIO	1200-38-9	SPECIFICATION No.	
REGISTRATION No.		MAKE & MODEL		YEAR	1940	TYPE	T E TRAINER
			SOLD			MANUFACTURERS No.	R 9950