

**OVERHAUL DATA**

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

**ACCIDENT RECORD**

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
7.7.42	B	Braunford Road	1115	58733s A77	7/7	Lac J C Gentil	2		

B. S. LTD.

**AIRCRAFT RECORD CARD**

PAT'D 1920

**REMARKS**

*Re Acc. 1 - 4c Anson III 6049 swung on approaching to land and struck tin parked 4c. Engine installed Cheetah IX 10089/51849*

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE'S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREWS (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>de Havilland, Toronto</i> DATE <i>13.8.41</i>			TRANSFER ORDER No. <i>2294</i>		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>20.10.41</i>	<i>#IT.C</i>	<i>#58FT T.O. 3276</i>			
<i>21.8.41</i>	<i>APDAL</i>	<i>#110 T.O. 15620</i>			
<i>22-1-45</i>	<i>APDAL</i>	<i>#1A2 T.O. 18156</i>	<i>17862(C)</i>	<i>1271</i>	
<i>22-1-45</i>	<i>has parts for repair</i>	<i>T.O. 18156</i>			
	<b>DEC. SER NO</b>	<b>GR 2-24</b>			

REMARKS

*Hours since Mtd: 2083.05*  
*of haul: Nil*

*U.S. Contribution*

*Location: 5 S.F.I.B.*

ENGINE TYPE	<b>CHEETAH IX</b>	UNITS	<b>2</b>	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH	<b>TP 223</b>	LEDGER FOLIO	<b>1200-38-9</b>	SPECIFICATION No.	
REGISTRATION No.	<b>6838</b>	MAKE & MODEL	<b>ANSON I</b>	YEAR	<b>1941</b>	TYPE	<b>T E TRAINER</b>
			<b>SOLD</b>			MANUFACTURERS No.	<b>AW 491</b>