




20728(18728)

ARGUS

MK2

CAIR

RCAF REGISTRATION NUMBER

TYPE

MARK

Only No - 19

RECORD OF TRANSFERS

DATE	AUTHORITY	IE ALLOTTED TO	REMARKS
17/2/59	QTO 1097	MAC - 405 <i>San Greenwood</i>	
2/12/60	QTO 788	Canadian <i>for receipt of all outstanding</i>	
24/4/61	QTO 156	MAC - 405 <i>San Greenwood</i>	<i>except Stand 6A</i>
10/4/62	QTO 788	<i>Indefinite</i>	<i>A/C is available for delivery</i>
25/4/62	QTO 196	Fairly A - CAIR & Mods	
31/8/62	QTO 516	MAC - 405 <i>San Yund</i>	
5/8/65	QTO 394	Canadian - <i>Can. Air.</i>	
5/9/65	QTO 564	MAC - 405 <i>San Yund</i>	
29 June 66	QTO 293	WR&RS - <i>Purple WFT</i>	
29 June 66	QTO 293	Fairly <i>Canada</i>	
27 Oct 66	QTO 483	MAC - 405 <i>San Yund</i>	
20 Sep 66	QTO 409	Can - <i>Partington</i>	
20 Sep 66	QTO 409	MAC - 405 <i>San Yund</i>	
16 July 68	<i>Marcom</i>	<i>Marcom - 405 San Yund</i>	



RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT 1510-21-860-0415

DATE _____

QTO No.

CD No.

TRANSFERS

DATE _____

QTO No.

TO

4 Aug 78

210175

СТУПЕНЬ

708703

70804

70815

720812

~~37m 70~~

QFO-12

MF 11/11

21-27

720812

7039

0-090

70810
MFC

11 22 13

19

7081151

8112

2 Feb 81

1050212

Discreet Lesson

to CAD/C

TRANSFERS

DATE _____

QTO No.

TO

airframe only

E A

MANUFACTURERS No. 19

CD No. 962007

TRANSFERS

708017, 708042, 708155, 708010

OVERHAUL DATA

DATE	QTO NO.	CONTRACTOR	REPAIRS
2 Dec 60	788	Canadaair 979888	for retrofit of all outstanding approved modifications except 5 and 6A other than those annotated for contractor, retrofit of equipment not installed on production is available and numerous repairs required for flight safety.
10 apr 62	143	Fairly Aviation	179807
25 apr 62	196	Fairly +	179807
5 aug 65	394	Canadaair	179807
20 Sep 66	409	Canadaair	579807
24 Sep 69	Q10348	Fairly	879807
13 Jan 71	Q10483	Industrial Manufacturing	2799807
17 Aug 73	Q10255	ILP Portsmouth	2792807
3 apr 74	Q10102	ILP Portsmouth	2793807
			for retrofit of all outstanding approved modifications except 5 and 6A other than those annotated for contractor, retrofit of equipment not installed on production is available and numerous repairs required for flight safety.
			32 PM, mod work on definite work package
			6+11K 05-1204-7B
			made t.d.W.
			Painting
			DRL of Mod.
			For work package, for 3, 6F20 letter 11500 BR-393/72
			D.L.R.D
			D.L.R. + ^{AWB} aerospray. Removal of cells 7, 8 & 9

THE OFFICE SPECIALTY MFG. CO., LTD. 26346 L

CFHQ DAM 322236 04/13002 Jan 70 - New Registration No-

7-8-79 Q10201

for controlled cannibalization