

**OVERHAUL DATA**

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
24.6.42	Crash	Central Aircraft					

**ACCIDENT RECORD**

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
8.6.42	B	5.0m SE Fingal Ont	1530	4895sA65	8/6	S/PER Ops	2	Central 7c	

B. S. LTD.

**AIRCRAFT RECORD CARD**

PAT'D 1920

**REMARKS**

Re. acc. 1. - Eng. inst. 2827/8266 Failure of hydraulic pressure line from pump. Made forced landing.  
 1.2.43 Allotted for installation of gun turret

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT #6 H.B.D. Trenton	DATE 14.11.40	TRANSFER ORDER No. 2644			
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
12/11/40	#1 Training Command	T.O. 5028			
24.6.42	Central of Drumlin	T.O. C 673			
1.2.43	#9 R.D. St. Johns W. Res 13/3	T.O. 5307			
7.9.43	Stores Reserve #3TC	T.O. 3230			
26-7-44	HPDAL (no. 3TC.)	T.O. 14966			
4.11.44	WAR ASSETS CORPORATION	T.O. 16992			

REMARKS for estab. # 19 # 1  
 7/9/43:- CONVERTED TO GUN BATTLE.5

U.K. Contribution

Hrs:-  
 Since New - 500  
 " overhaul -  
 Location - #9 R.D.

ENGINE TYPE MERLIN III	UNITS	AIRSCREW TYPE (code)	REF. No.
BATCH No.	QUAN. IN BATCH TP 1	LEDGER FOLIO 1200-38-1	SPECIFICATION No.
REGISTRATION No. 1716	MAKE & MODEL BATTLE I T	YEAR 1940	TYPE S E BOMBER (GUM)
	SOLD		MANUFACTURERS No. N 9326