

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
18 Sept 47	1/2 hr. inspection to radio room	Frank H. [unclear]	APPB 28562				
1 Nov 48	2 ps repairs	Canadian	APPB 28563		N. 1410.40	26 May 48	NWA
Dec 48	3 radio unit on job 10-48	YSLORA -				19 Feb 49	NWAC
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	AIRCRAFT TYPE	NUMBER	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

MAJOR EQUIPMENT RECORD CARD

REMARKS

29 Aug 47 - 10 RD's - 1038 JA (RSS) on 1038 JA-1.7 " SCR 729A, AN/APN-4 voltage control panel SCR 224N, PC 375E, PC 348R, SCR 2696, +R1143A, PC 357 (A), PC (English) RTT/APN-1 " Done in 10. No wiring for this set.

14 Nov 47 - T. 30. 1414. 07.

6 Jan 48. In modification to Spec 877-1-4 and reconditioned to R6-1-1

31 Mar 49 - a page 757 - 199435; T30. 50. 40

