

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
10 Oct 48	Condition and to spec AM-1-3	Canadian	CR 1426			16 Mar 49	CAC
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	AIRCRAFT TYPE	NUMBER	DISPOSAL	DATE SERV.
26-6-51	A	Summerside		7737	26/6/51				
2									
3									
4									
5									
6									
7									
8									

MAJOR EQUIPMENT RECORD CARD

REMARKS

29 Aug 47 - 10 RD's. 1038/0.1755 to 1038/0.1757, SCR 729A, AN/APN 4, VFR (English) voltage control panel, SCR 274N, DC 375E, DC 348R, SC 269G, SCR 522, DC 357H, Packard Del int. com. RC 103A, AN/APR1

27 Sept 47 - 10 RD's. 0999 to 1035/0.1-3, equipped and fitted, with tow release mechanism. (42D 1200)

19 Jan 48 - 10 RD's. 1713.05, Condition: Fair. Original Std.

REMARKS:

## RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T.O. No.

## DISPOSAL PARTICULARS

REMARKS:

EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 233 54-11-17 (5416) H.O. 985 F. 233

LOWE-MARTIN M'FG

## MAJOR EQUIPMENT RECORD CARD

FIRST ENTRY AT STORED RESERVE MC NO 10 R.D. (WEYBURN) DATE 26 AUG 46 TRANSFER ORDER NO. MC 12377

## TRANSFERS

## TRANSFERS

DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
1 Oct 48	NO 11 T.S.U. (CANADAIR)	T.O. MC 12397			
16 May 49	C.A.C. AS per memo	TO AMX 12096			
6 July 51	R/D - special procedure	TO 1209			

REMARKS: 26-8-46--RECEIVED FROM RCAF OVERSEAS.

41795 B  
352830

Ref no. 38184

TYPE OF EQUIPMENT IN WHICH USED	WASP R1830-92				
BATCH NO.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION NO.		
REGISTRATION NO.	MAKE & MODEL	YEAR	TYPE	MANUFACTURER'S NO.	
	WYBURN			42-92642	

Dof - Snatch  
Gear -

NRAC 51

June 15 - conversation

by McMorris & McMorris

Snatch Gear can  
be changed from  
one Doherty to any  
other that has been  
modified for such  
an installation.

Chase has 3 such  
etc but only Doh  
KG 441 is completely  
equipped & serviced  
in this regard.

If system is complete  
then wrenches can be  
replaced in approx  
3 hrs.

The following is a list of the  
 names of the persons who  
 have been appointed to the  
 various committees of the  
 Board of Directors of the  
 R. L. Grain Limited for the  
 year ending 31st December  
 1940.