

HB 109

BEECHCRAFT UC-45 EXPEDITER (C-45)

1944

T E TRANSPORT.

5628 (43-35478)

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1 Mar 48	Reconditioning Modifications	Wm Donald Bros.	W. 720		T.S.N. 461.00.	25 Apr 49	77 WAC
20 Feb 50	to Spec. RM-1-S assembly	Wm Donald Bros.	AMC Reg. 411 clw				
27 May 53	reconditioning 1 mod spec RM-29	TABA	511961			31 May 54	TC
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
1									
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Equipped with single cylinder type automatic pilot servo
 of type T.S.N. - 461.00. - 20-100-1000 for fuselage mod record Bros.
 for modification to Spec RM-1-S and Reconditioned etc
 Spec RM-1-S

REMARKS:

RECORD OF WRITE-OFF							
APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

R.C.A.F. E. 293D - 6M-1.43 (3025) H.Q. 965 - E-293

AIRCRAFT RECORD CARD

FIRST ENTRY AT *D.A.C. (#32024)* DATE *5. 1. 44* TRANSFER ORDER NO. *6460*TRANSFERS *various*

TRANSFERS

DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
3.2.44	Converted to synthetic Trainer	T.O. 7221	16 Nov 50	WAC	TO 1403
5.4.44	D.A.C. (#32024)	T.O. 12216	20 Aug 52	AMC (CE/PF det (Relton))	ATO-1386
26.5.44	Converted synthetic Trainer	TO 13621	27 May 53	1015U (MBA)	ATO-1135
1.8.45	Comox B.C. WSR.	T.O. B216	31 Mar 54	AB TC	OTO-1985
3.10.45	S.R. WAC	T.O. 15235	31 Jan 56	SR GRD	QTO-682
29.11.45	Stand Reserve MC (Abbots Farm)	TO MC 15885	29 Nov 56	Stand Reserve GRD	QTO 641
14.1.46	Stand Reserve MC (716210)	Q2069 31.5.1			
14.1.48	W.S.R. No 10 RFL	TO MC 12711			
17 Mar 48	11 Exp D. (M. Donald Bros)	MC 12804			
25 Apr 49	WAC	TO AMC 12056			
25 Jun 50	145D (MacDonald Bros)	TO 1169			

REMARKS: 3/2/44:- THIS AIRFRAME IS TO BE CONVERTED TO A SYNTHETIC TRAINER. AUTHORITY ON A.F.H.Q. FILE 441-4-6. THIS AIRFRAME IS TO BE RETURNED TO SERVICE WHEN A LESS REPAIRABLE CRASHED AIRFRAME BECOMES AVAILABLE.

5/4/44:- RETURNED TO SERVICE.

3.10.45- Serviceable.

26/5/44:- CONVERTED AGAIN TO SYNTHETIC TRAINER.

1-8-45 Returned to Service (an Equip 20858)

382548 file 736

Misc 858

U.S.A. No. 43-35478

ENGINE TYPE	WASP R985-AN-3	UNITS	2	AIRSCREW TYPE (CODE)	200374	REF. No.	
BATCH No.	QUAN. IN BATCH: USA 638	LEDGER FOLIO	714-Misc-USA 638	SPECIFICATION No.			
REGISTRATION No.	8/3/23/15	MAKE & MODEL	BECHDRAFF-UC-45-B EXPEDITER (SYNTHETIC)	YEAR	31	TYPE	A/T
HB 109						MANUFACTURERS No.	5828 (43-35478)

HB 109

EXPEDITER
3TWASP
R985-AN14B43-35478 2
5828

RCAF REGISTRATION NUMBER

MAKE AND MODEL

ENGINE TYPE

MANUFACTURERS No.

INITIAL ENTRY AT

DATE

QTO No.

CD No.

TRANSFERS

TRANSFERS

DATE	QTO No.	TO	DATE	QTO No.	TO
21 Nov 56	910-641	Inactive Power 6RD			
7 Nov 58	740	WR 6RD			FILE L 10026-18-B-0-69 TD 9036
9 Feb 59	1058	SR 6RD			Letter 266-358-66-9 16 May 69.
6 Apr 59	117	to cancel by Service to engine to New location			Waived off Loan Agreement
20 May 59	261	WR 6RD			{ Del 18-8-0-67 2F-PW7.
20 Oct 59	703	SR 6RD			Loan agreement cancelled for period
8 July 60	360	11754 C.L.W. C.A.			pending 31 Mar 1970
1 Dec 70	438	of del united of del ^{Longueuil} Canada Ltd			FILE 366-358 5 Feb 70 Letter from T. Hall
2 10 126	2 10 431	<u>ME 5964</u>			control dir (10026-18-B-0-67. transmitted to 31 Mar 71
1 1/2 Mar 71	870311963	6406 sold to:- united aircraft of Canada Ltd P.O. Box 10 Longueuil, Quebec			Loan cancelled & interest against loan rep

