

237

FAWN II

(WRITE-OFF)

1937

ELEM TRAINER

91

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

## ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	No. IN CREW	DISPOSAL	DATE SERV.
2/11/37	"A"	Trenton	0943	Radio 1838		2nd Lt Taylor			
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Be Crash No 1 - Submersion crash - low flying alleged cause.  
 Serial 2135 23/11/37 states aircraft - damaged beyond economical  
 repair following crash into Bay of Quinte.  
 Total flying hours 68%

RECORD OF WRITE-OFF							
APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
RCAF Trenton	1-12-37	1021-4-363	7-2-38	CAE		6-2-38	DRO 34
DISPOSAL PARTICULARS							
AIRFRAME	Produce						T. O. No.
ENGINE(S) (QUOTE SERIAL NOS.)	Engine salvaged and repaired						T. O. No.
AIRSCREW(S) (QUOTE SERIAL NOS.)							
ACCESSORIES	Instruments salvaged to Depot						
REMARKS:							EFFECTIVE DATE WRITTEN-OFF 6-2-38

AIRCRAFT RECORD CARD					
FIRST ENTRY AT		DATE	TRANSFER ORDER No.		
Borden		14.4.37	RV B 33, 875		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
10-8-37	Trenton	M.O 155			
10-8	C. Flight F.T.S. No. 155	155			
19-8	C Flight FTS	184, 189			
22-11	Stores Unserviceable	226			
REMARKS					

ENGINE TYPE	UNITS	AIRSCREW TYPE (CODE)	REF. No.
CIVET 1A	1		
BATCH No.	QUAN. IN BATCH	LEDGER FOLIO	SPECIFICATION No.
	CO 798	700-38-89	
REGISTRATION No.	MAKE & MODEL	YEAR	TYPE
237	FAWN II (WRITE-OFF)	1937	ELEM TRAINER
			MANUFACTURERS No.
			91