

259

FAWN II

(WRITE-OFF)

1938

ELEM TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
3/12/40	D	Porters Field	0830	CAS sig A 923	5/12	Sgt C. S. Shannon	1		
3/16/41	A "B"	Porters Field	1635	CAS sig A 204	24/16	PO. H. R. J. Staden	solo	spanning	
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc 1:- Hit trees with underscarriage and crashed.
 I.D. C 731 states crash category as "A"
 Re Acc 2:- Engine installed - Asset 1A - no. 22022/575.

REMARKS: involved in "A" crash at Potters Field 23/6/41.

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
LRD (E 107)	14/7/41	1038AE-259	9.10.41	S.H.S.O., ITC	"LRD"	17.10.41	C 731

DISPOSAL PARTICULARS

AIRFRAME	Reduced to spares and produce	T. O. No.	2011
ENGINE'S (QUOTE SERIAL NOS.)		T. O. No.	
AIRSCREW'S (QUOTE SERIAL NOS.)			
ACCESSORIES			
REMARKS:	Reduced to spares and produce in accordance with I.T.C. letter 1038 AE-259 (Eq 1), 16/10/41	EFFECTIVE DATE WRITTEN-OFF	

AIRCRAFT RECORD CARD

FIRST ENTRY AT			DATE	TRANSFER ORDER No.		
Camp Borden			11/6/38	DRO 113		
TRANSFERS			TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY	
3/6/38	118 (B) Squadron	J.C. 337				
23/1/39	Camp Borden	J.C. 1002				
27/2	118 (B) Squadron	J.C. 1108				
26/10	103 (F) Squadron	A 154				
2/2	J.I.S. Camp Borden	A 232				
22/1/40	R.G.A. Lt. Drenton	A 361				
22/1	J.I.S. Lt. Drenton	A 370				
1/4	Rec. Training Command					

REMARKS

ENGINE TYPE	QIVET 1A	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH	CO 92	LEDGER FOLIO	700-38-99	SPECIFICATION No.	
REGISTRATION No.	259	MAKE & MODEL	FAWV 11 (WRITE-OFF)	YEAR	1939	TYPE	ELEM TRAINER
						MANUFACTURERS No.	