

(1021) A 235

FINCH I

(INSTRUCTIONAL) SOLD

1940

ELEM TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
30.4.41	Crash	Fleet Aircraft			681 ³⁰	9.7.41	1 ITC
2.2.42	Mech Failure	Fleet 9c			1187 ³⁵	5.4.42	1 ITC
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
19.4.41	"B"	Bellefleur, Ont	1145	C.F.S. SA 671	21/4	Sgt J A Robertson	1	Fleet 9c	9.7.41
17.6.42	C 4	C.F.S. Trenton Ont.	1655	C.F.S. SA 795	19/1				
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

23.10.41. RCAF Trenton signal A249. Aircraft swung back while kicking propeller. AC2 Rogers who was servicing 9c suffered slight laceration to thumb.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION REC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
DISPOSAL PARTICULARS							
AIRFRAME							T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)							T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)							
ACCESSORIES							
REMARKS:							EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>Camp Borden</i>			DATE <i>16/2/40</i>	TRANSFER ORDER No. <i>104</i>		
TRANSFERS			TRANSFERS			
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY	
<i>1/4/40</i>	<i>No. 1 Training Command</i>					
<i>30.4.41</i>	<i>3 Fleet Aircraft, Ft. Erie</i>	<i>T.O. C.66</i>				
<i>9.7</i>	<i>#1 TC Trenton</i>	<i>T.O. 1552</i>				
<i>22.4.42</i>	<i>3 Fleet 7-Crumlin 14/2</i>	<i>T.O. C.1130</i>				
<i>19.10.42</i>	<i>3 Fleet #1 JC 19/10</i>	<i>T.O. 3467</i>				
<i>3.12.42</i>	<i>Converted Instructional</i>	<i>T.O. 4235</i>				
	<i>Stored Reserve H.Q.C.</i>					
<i>31.1.45</i>	<i>Upd. #1 A.C.</i>	<i>To 18279</i>				
<i>18.6.46</i>	<i>Spd. MC (6 R.D.)</i>	<i>To MC 12329</i>				
<i>3 Sept 46</i>	<i>War Assets</i>	<i>To MC 12898</i>				

REMARKS

*H. v. s.
Since new
I had out
location + 6 R.D.*

ENGINE TYPE <i>KINNER K5-2</i>	UNITS <i>1</i>	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH <i>600</i>	LEDGER FOLIO <i>700-38-123</i>	SPECIFICATION No.
REGISTRATION No. <i>(1021) A 235</i>	MAKE & MODEL <i>BENCH 1 (INSTRUCTIONAL)</i>	YEAR <i>1940</i>	TYPE <i>ELEM TRAINER</i>
MANUFACTURERS No.			