

4461	FINCH II	SOLD	1940	ELEM TRAINER	
REGISTRATION NO.	MAKE & MODEL	YEAR	TYPE		MANUFACTURERS NO.

OVERHAUL DATA							
DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
26.6.42	Time Exp.	Can. Cars Fdy			1500 ⁰⁰	19.10.42	EAC S.R.
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD									
DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO IN CREW	DISPOSAL	DATE SERV.
30/5/41	"C"	Windsor Mills P.Q.	1040	4EFTS, SA249	31/5	F/Lt. R. Simard	1		
16.7.41	"C2"	Brompton, Que	1810	4EFTS, SA350	17/7	LAC A. Bossenberry			
30.5	"C3"	Windsor Mills Q.	1040	4EFTS, SA249	31/5	F/Lt. R. Simard	1		
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc 1: - Finch 4461 collided with Finch 4477 when landing. Eng. installed - Kinver 25 N 1625/16215.
 Re Acc 3: - Crash already posted.
 7. 12. 43. Allotted to #988, St. John's (C. Res.) pending write off.

REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.
DISPOSAL PARTICULARS							
AIRFRAME							T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)							T. O. No.
AIRSCREW/S (QUOTE SERIAL NOS.)							
ACCESSORIES							
REMARKS:							EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>RCAF Sta. Trenton</i>		DATE <i>2/6/40</i>	TRANSFER ORDER NO. <i>409</i>		
TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>25/6/40</i>	<i>#3 Training Command</i>	<i>T.O. 576</i>			
<i>26/6/42</i>	<i>Can Can 744</i>	<i>TO 1459</i>			
<i>19.10.42</i>	<i>Stored Reserve E.A.C.</i>	<i>TO 3438</i>			
<i>2.3.43</i>	<i>Stored Reserve #3 T.C. 14/2</i>	<i>T.O. 5887</i>			
<i>19.7.</i>	<i>#3 T.C.</i>	<i>T.O. 2302</i>			
<i>7.12.43</i>	<i>#9 R.D. St. John's (St. Res.)</i>	<i>T.O. 5691</i>			
<i>11.4.44</i>	<i>ATDAL #3 T.O.</i>	<i>E.O. 12139</i>			
<i>17.10.44</i>	<i>War Assets Corp</i>	<i>T.O. 16662</i>			
	<i>- G. Babb & Co.</i>				

REMARKS

Hrs: Since New: 1:35
" overhaul: -N.A.

Cost

Location: - No. 3 T.C. 9 R.D. B.C.A.T.P.
St. John's Que

ENGINE TYPE <i>KIPPER 85R</i>	UNITS <i>1</i>	AIRSCREW TYPE (CODE)	REF. No.
BATCH No.	QUAN. IN BATCH <i>TP 4</i>	LEDGER FOLIO <i>1200-38-3</i>	SPECIFICATION No.
REGISTRATION No. <i>4481</i>	MAKE & MODEL <i>PRIMA II</i>	YEAR <i>1940</i>	TYPE <i>ELEM TRAINER</i>
	<i>SOLD</i>		MANUFACTURERS No.