

# CASPIR.warplane.com

## CASPIR Aircraft Record Cards

---

**Serial:** 3590

**Title:** Fleet Fort serial:3590 Aircraft Record

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** Taken on Strength: 1941-12-30. This accident involved 1 aircraft on 1943-August-24. Fleet Fort II s/n 3590. This accident involved 2 people. Roberts VG, Wright WR

**Keywords:** Fort ,3590,1941-December-30,Roberts,Wright

**Created:** 1941-12-30

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3590>



REMARKS:

RECORD OF WRITE-OFF

APPLICATION RC'D FROM	DATE	FILE No.	DATE APPROVED	APPROVED BY	APPROVAL SENT TO	DATE	T. O. No.

DISPOSAL PARTICULARS

AIRFRAME	T. O. No.
ENGINE/S (QUOTE SERIAL NOS.)	T. O. No.
AIRSCREWS (QUOTE SERIAL NOS.)	
ACCESSORIES	
REMARKS:	EFFECTIVE DATE WRITTEN-OFF

AIRCRAFT RECORD CARD

FIRST ENTRY AT <i>#4 J. G.</i>	DATE <i>30.12.41</i>	TRANSFER ORDER No. <i>13085</i>
--------------------------------	----------------------	---------------------------------

TRANSFERS			TRANSFERS		
DATE	TO	AUTHORITY	DATE	TO	AUTHORITY
<i>14.3.44.</i>	<i>#106.1 (w.w.s.) Col. G. G. G.</i>	<i>T.O. 3759</i>			
<i>14.6.44.</i>	<i>Apdal #4 J. G.</i>	<i>T.O. 14084</i>			
<i>1.12.44</i>	<i>APDAL No. 2 AIR COMMAND</i>	<i>P.O. 17328 (6)</i>			
<i>5.2.45.</i>	<i>Wear Assets Corporation</i>	<i>T.O. 18360.</i>			

REMARKS SHIPPED TO #10 R.D. FOR WIRELESS INSTALLATION.

Hrs. Since New - 1076.20  
 " 01Haul N.A.

Purchased

Location - 10 Repair Depot

ENGINE TYPE	JACOBS L6-MB	UNITS	1	AIRSCREW TYPE (CODE)		REF. No.	
BATCH No.		QUAN. IN BATCH	TP 860	LEDGER FOLIO	1200-38-14	SPECIFICATION No.	
REGISTRATION No.	3590	MAKE & MODEL	FORT II	YEAR	1941	TYPE	SE TRAINER, WIRELESS
			SOLD			MANUFACTURERS No.	