

2567

HARVARD II

TRANSFERRED TO R.A.F. (WRITE-OFF)

1940

S E - TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
17/3/41	1	Buttress Relief L.G.	1245	#32216/16/14493	17/3	PAC. J. Smith.			
15.8	2	6mi. SE. of Boharm, Saab	0900	32SFTS 9347	13/8	LAC. P.V. Sandeman		Spares + produce	
	3								
	4								
	5								
	6								
	7								
	8								

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

15/8/41: - Inspection Report from #4 T.C. recommends that this airframe be written-off after collision.
 Flying time 806 hrs
 R. Acc. 2: - w/c 2567 collided (in error of judgement) of w/c 2627
 Engine installed - Prop S3401 no 7904/4084.
 Total Flying Time: - 805⁵⁰ hrs (auth. Log Book).

