

2644

HARVARD 11

(WRITE-OFF)

1940

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
15.3.43		Roarwyn W.				25.543	# I.T.C.
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
7/12/40	1 D3	Uplands	0805	25776 sig. 1149	7/12	1/0 B. Sparker	1		
24.9.41	2 "C2"	Uplands Aerod	1430	25975 s. A589	24/9	IAC DM. Hall	-		
20.5.42	3 "C11"	Uplands Aerod	1400	25775 s. A789	20/5				
10.9.44	4 "B"	#18.2.2.2.			10/9/44				
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 3. - Pilot of '9c Harvard taxied into this '9c when preparing to take off. '9c. 2644 was stationary.
2.9.44: Accident to #6 (R. Lewis) for uninitiated start of action.

