

2647

HARVARD 11

(WRITE-OFF)

1940

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
10.4.41	"C7"	Borden Out.	1150	*1SFTS, & C48	10/4	LAC F. Pettem	1		
11.6.41	"C1"	Camp Borden	1515	*1SFTS, & A158	12/6	3/09 W. Weig	1		
11.2.42	"B"	Edenville Out	2020	157755 C.19	12/2	Sac H. Smith			
26.5.	"B"	Thornton Out	1600	157755 C.93	28/5	P/O J. Wright	1	6 RD Wrote off.	
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 3: - This ac collided with Harvard, 3/84 on runway due to other ac being stuck in snow.

Re. acc. 4: ac eng. caught fire. Pilot put it out but had to make forced landing due to smoke. Struck a rock.

